


PART INFORMATION

No : 023 / PI / PART / IAMI / III / 15
 Tanggal : 9 Maret 2015
 Perihal : PTO FLYWHEEL, FVZ MIXER (INLINE)

FIG.NO : 0-90 POWER TAKE OFF; FLYWHEEL



NO	PART NEW	DESCRIPTION	FIG No.	KEY NO.	APPLIED DATE	RETAIL	REMARKS
1	I8-98011 447-1	POWER TAKE OFF ASM FVZ N	0-90	001	1402-	Rp21.100.000	6HK1
2	I9-09720 519-0	GASKET; BRG CASE FVZ-N (M	0-90	004	1402-	Rp104.000	6HK1
3	I8-97388 533-0	OIL SEAL PTO CXZ	0-90	005	1402-	Rp52.000	6HK1
4	I8-98011 439-0	BEARING; FLYWHEEL PTO FV	0-90	006	1402-	Rp265.000	6HK1
5	I8-98066 078-0	BEARING; FLYWHEEL PTO FV	0-90	006	1402-	Rp400.000	6HK1
6	I8-98011 441-0	GEAR; FLYWHEEL PTO FVZ-N	0-90	008	1402-	Rp5.700.000	6HK1
7	I8-98011 444-1	SHAFT; PTO, FLYWHEEL FVZ-	0-90	011	1402-	Rp3.050.000	6HK1
8	I8-98011 449-0	THROWER; OIL, FLYWHEEL P	0-90	016	1402-	#N/A	6HK1
9	I1-38189 010-2	FLANGE; PTO, FLYWHEEL CY	0-90	017	1402-	Rp1.950.000	6HK1
10	I8-94396 895-1	SPINDLE; IDLE GEAR, PTO	0-90	029	1402-	#N/A	6HK1
11	I8-97600 138-0	COVER; FLYWHEEL HOUSING	0-90	034	1402-	Rp1.175.000	6HK1
12	I8-94396 903-0	PACKING; COVER, FLYWHEEL	0-90	035	1402-	Rp42.000	6HK1
13	I9-00032 209-A	BEARING HUB IN RR, NHR55	0-90	047	1402-	Rp210.000	6HK1
14	I8-98011 442-0	GEAR; IDLE A FVZ-N (MIXER)	0-90	050	1402-	Rp4.300.000	6HK1
15	I8-98011 446-1	CASE; BRG, PTO FVZ-N (MIXE	0-90	052	1402-	Rp5.750.000	6HK1

* Detail part dapat dilihat di : <http://catalog.isuzuastraparts.com>