PT.ISUZU ASTRA MOTOR INDONESIA
PART DEPT.

ISUZU GENUINE PARTS

PART INFORMATION

No : **028 / PI / PART / IAMI / IV / 15**
Tanggal : **6 April 2015**
Perihal : LAMP TURN SIGNAL, F#

FIG.NO : 8-01 LAMP; FRONT AND FRONT SIDE



FTR; FVR; FVM; FVZ; GVR; GVZ
Without Lamp Signal Hole

FRR
With Lamp Signal Hole



NO	PART NEW	DESCRIPTION	FIG No.	KEY NO.	APPLIED DATE	RETAIL	REMARKS
1	*I8-98181 878-A*	*LAMP TURN SIGNAL RH*	*8-01*	*331*	*1104-*	*Rp275.000*	*FTR; FVR; FVM; FVZ; GVR; GVZ*
2	*I8-98181 879-A*	*LAMP TURN SIGNAL LH*	*8-01*	*331*	*1104-*	*Rp275.000*	
3	*I8-98155 458-A*	*LAMP TURN SIGNAL RH*	*8-01*	*331*	*1103-*	*Rp300.000*	*FRR*
4	*I8-98155 459-A*	*LAMP TURN SIGNAL LH*	*8-01*	*331*	*1103-*	*Rp300.000*	